



SYRACUSE UNIVERSITY BOLAND HALL



2015 RESIDENCE HALL FIRE SAFETY REPORT

Building Name: Boland Hall	Address: 401 Van Buren St
Building Size: 9 floors plus basement and sub-basement, 6 exits	Building Capacity: 312

FIRE PROTECTION SYSTEMS

Sprinkler System: **Wet system throughout building including 100% of student rooms; 2 pre-action dry systems cover the electrical vault and the elevator mechanical room**

Fire Pump: 1,000 GPM Electric Flow Meter	Fire Alarm Control Panel: EST-3
Addressable Pull Stations: 29	Sprinkler Supervisory: 23
Photo-Electric Smoke Detectors: 122	Water Flow Switches: 14
Heat Detectors: 25	Roof Hatches: 0
Duct Detectors: 0	Fire Shutters/Louvers: 0
Alarm: Horns w/Visual: 61	Beam Detectors: 0
Fire Extinguishers: 33	Alarm System Type: Campus Tie
Ansul Systems: 0	Inspections Requirements: NFPA 72 (1 thru 7)


INSPECTION, TESTING, & MAINTENANCE

Evacuation Drills:	2/19/15	4/3/15	10/6/15	11/4/15
Smoke Detection Certification:	5/12/15			
NYS Office of Fire Prevention and Control Inspection: 10/14/15				

FIRE ALARMS

Date	Cause	Date	Cause
2/7/15	Cooking	2/13/15	Sprinkler
2/25/15	Malicious	3/5/15	Unknown
3/15/15	Unknown	4/10/15	Unknown
5/3/15	Unknown	10/11/15	Unknown
12/3/15	Cooking		

2015 Fire Alarms



■ Unknown ■ Cooking ■ Accidental ■ Malicious