



SYRACUSE UNIVERSITY SADLER HALL



2015 RESIDENCE HALL FIRE SAFETY REPORT

Building Name: Sadler Hall	Address: 1000 Irving Ave.
Building Size: 9 floors plus basement, 8 exits	Building Capacity: 471

FIRE PROTECTION SYSTEMS

Sprinkler System: Wet system throughout building including 100% of student rooms; 2 pre-action dry systems cover the electrical vault and the elevator mechanical room	
Fire Pump: 1,000 GPM Electric Flow Meter	Fire Alarm Control Panel: EST-3
Addressable Pull Stations: 33	Spk. Supervisory: 24
Photo-Electric Smoke Detectors: 190	Water Flow Switches: 17
Heat Detectors: 60	Roof Hatches: 3
Duct Detectors: 3	Beam Detectors: 0
Alarm: Horns w/Visual - 91	Alarm System Type: Campus Tie
Fire Extinguishers: 34	Inspections Requirements: NFPA 72 (1 thru 7)
Ansul Systems: 1	


INSPECTION, TESTING, & MAINTENANCE

Evacuation Drills:	2/26/15	3/30/15	10/7/15	11/3/15
Smoke Detection Certification:	8/5/15			
NYS Office of Fire Prevention and Control Inspection: 10/9/15				

FIRE ALARMS

Date	Cause	Date	Cause
1/30/15	Sprinkler	2/24/15	Accidental
3/26/15	Accidental	5/3/15	Unknown
5/9/15	Unknown	6/9/15	Contractor
6/22/15	Unknown	7/27/15	Contractor
8/4/15	Contractor	8/6/15	Contractor
8/28/15	Cooking	9/1/15	Unknown
9/7/15	Unknown	11/23/15	Contractor

2015 Fire Alarms



■ Unknown ■ Accidental ■ Contractor ■ Cooking ■ Sprinkler