



SYRACUSE UNIVERSITY WALNUT HALL



2015 RESIDENCE HALL FIRE SAFETY REPORT

Building Name: Walnut Hall	Address: 809 Walnut Ave.
Building Size: 4 floors plus basement, 3 exits	Building Capacity: 46

FIRE PROTECTION SYSTEMS

Sprinkler System: Wet system throughout building including 100% of student rooms.	
Fire Pump: 1,000 GPM Electric Flow Meter	Fire Alarm Control Panel: FCI
Addressable Pull Stations: 7	Spk. Supervisory: 2
Photo-Electric Smoke Detectors: 38	Water Flow Switches: 1
Heat Detectors: 4	Roof Hatches: 0
Duct Detectors: 0	Fire Shutters/Louvers: 0
Alarm: Horns w/Visual – 10	Beam Detectors: 0
Fire Extinguishers: 9	Alarm System Type: Campus Tie
Ansul Systems: 0	Inspections Requirements: NFPA 72 (1 thru 7)

INSPECTION, TESTING, & MAINTENANCE

Evacuation Drills:	2/16/15	3/27/15	10/6/15	11/5/15
Smoke Detection Certification:	5/15/15			
NYS Office of Fire Prevention and Control Inspection: 10/14/15				

FIRE ALARMS

Date	Cause	Date	Cause
4/11/15	Electrical	10/29/15	Unknown

2015 Fire Alarms

